

Welcome:

X-RAY DIFFRACTION
RESIDUAL STRESS MEASUREMENT OF
SHOT PEENED COMPONENTS

ABOUT PROTO

Specializing in X-ray diffraction systems for over 30 years:

- Residual Stress & Retained Austenite Measurement
- Laue Orientation of Single Crystal Materials
- Powder Diffraction
- X-ray Tubes
- Electropolishers

ABOUT PROTO

Customer Base:

- Over 500 X-ray Diffraction (XRD) systems installed around the world in automotive, aerospace, power generation, marine, military, research & university sectors.

Service Laboratories

- 6 service laboratories with 20 XRD systems available for contract measurement work. Fast turn around time, competitive pricing. (USA, Canada, Japan, India, China, Poland)

ABOUT PROTO

Accreditation:

- ISO/IEC 17025:2005 Residual Stress & Retained Austenite Measurement

Major contributors to following Residual Stress specifications:

- ASTM E915 (major contributor)
- ASTM E1426
- ASTM E2860
- ASM Handbook Vol. 11
- MFN Shot Peening handbook

ABOUT PROTO

Publications:

- Over 70 papers published in peer reviewed journals on residual stress and x-ray diffraction.

Patents:

- Worldwide patents on x-ray diffraction equipment and measurement techniques

Residual Stress

Finished Component:

- Dimensionally Same
- Alloy / Chemistry Same
- Microstructure Same

Part A : Good



Part B : Fails



Residual Stress Distribution Different

What is residual stress?

- Internal stress distribution locked into a material.
- Present even after all external loading forces have been removed.
- Result of a material obtaining equilibrium after it has undergone plastic deformation.

How does residual stress compare to applied stress?

- **Applied stress** is generated inside a material due to an **external** load. (often measured with a strain gauge).
- **Residual stress** is present **inside** the material regardless of loading.

Units of residual stress?

Force per Unit Area

MPa = Mega Pascals

or

ksi = thousands of pounds per square inch

1 ksi = 6.895 MPa

Stress can be thought of as a kind of pressure

Defining residual stress at a point.

Stress is a tensor.

Multiple values at a single point

6 independent values.

3 Normal stresses - 3 Shear stresses.


$$\sigma = \begin{pmatrix} \sigma_{11} & \sigma_{12} & \sigma_{13} \\ \sigma_{21} & \sigma_{22} & \sigma_{23} \\ \sigma_{31} & \sigma_{32} & \sigma_{33} \end{pmatrix}$$

How does residual stress affect a component?

Tensile (+) residual stress or the stress that is causing the material to be stretched or pulled is often **detrimental** in a component.

Compressive (-) residual stress or the stress that is causing a material to be compacted or pushed together is often **beneficial** in a component.

Tensile




Compressive

Types of Residual stress

Type I (Macro Residual Stresses): are the average over a group of grains in the material, ~mm scale.

Type II (Micro Residual Stresses): residual stress in one grain. It may vary from grain to grain because of the elastic and plastic anisotropy. May also develop in multi-phase materials as a result of the different properties of the different phases example: Titanium (Alpha vs Beta phase).

Type III (Micro Residual Stresses): Exist within a grain essentially as a result of the presence of dislocations and other crystalline defects.



How does residual stress affect a component?

- Net sum of all residual stresses across any cross section is always zero.
- Across any cross section of a component there is typically a residual stress distribution.
- Residual stress distribution affects performance.

How does residual stress affect a component?

- Residual stress sometimes as high as the yield stress of the material.
- Residual stress can often be **larger** than the applied stresses.
- Typical values of residual stress are anywhere between -1000 and +1000 Mpa
- Materials with higher yield points will retain higher residual stress.

Are residual stresses real stresses?

- **Yes:** from a material's point of view there is no difference between residual or applied stress, a material can only take so much stress...

$$\text{Stress}_{\text{total}} = \text{Stress}_{\text{residual}} + \text{Stress}_{\text{applied}}$$

- Atoms don't know the difference between external loads and internal stress.
- High levels of residual stresses can greatly alter the expected performance of a material.

How is residual stress created in a material?


| Cause | Example |
|---------------|--|
| Mechanical | Plastification of a material during machining. |
| Thermal | Difference in solidification of the material. (i.e. in a cooling casting) |
| Phase Changes | Precipitation / Phase transformation resulting in a volume change (i.e. Austenite to Martensite) |

Sources of residual stress during manufacturing


- Machining such as grinding, turning, milling
- Welding
- Rolling
- Forging
- Surface enhancements such as peening

**What do residual stresses look like from
manufacturing processes?**


Weld Stresses : Tensile residual stress in Heat Affected Zone (HAZ)



Evaluate Surface Treatments: Shot Peening




Evaluate Surface Treatments: Shot Peening



As Welded


Shot peened

Evaluate Surface Treatments: Shot Peening




Patents granted
and/or pending

Understand effects of mechanical working processes such as machining, grinding, rolling, forging, extruding




Crack Initiation and Propagation

Residual Stress - Effect on Cracks




Tensile residual stress
opens crack and increases
crack propagation



Compressive residual stress
closes crack and slows crack
propagation

Crack Initiation and Propagation



Crack Initiation and Propagation

Crack initiation phase: NDT can not detect yet
(Time in this phase highly dependent on residual stress)



Crack propagation phase: NDT can usually detect




Failure

What techniques are available to measure residual stress?

| <i>Technique</i> | <i>Time for One Measurement</i> | <i>Spatial Resolution</i> | <i>Depth of measurement</i> | <i>Best Accuracy (MPa)</i> | <i>Limitations</i> | <i>Calibration</i> |
|--|--|----------------------------------|---------------------------------------|-----------------------------------|--|---------------------------|
| <i><u>Ultrasonic</u></i> | 5 to 20 min | 0.1 to 30 mm ² | 60 to 300 µm | 10 to 20 | Microstructure effects Qualitative | Required |
| <i><u>Barkhausen</u></i> | 1 sec to 10 min | 1 mm ² | 0.1 to 1 mm | 10 to 20 | Non-ferromagnetic materials & microstructure effects Qualitative | Required |
| <i><u>Eddy Current</u></i> | 1 sec to 10 min | 1 mm ² | 60 to 200 µm | Unknown | Limited materials Material & microstructure effects Qualitative | Required |
| | | | | | | |
| <i><u>Neutron diffraction</u></i> | 5 min to 2 hrs | 1 mm ³ | 70µm to 30 cm in Al, 3 cm Steel | 10 to 20 | Depths greater than 1mm, texture and coarse grain size | Not Required |
| <i><u>X-ray diffraction</u></i> | 0.5 sec to 2 hrs | 0.5 mm ² or less | 5 to 30 µm | 5 to 10 | Texture and coarse grain size increase measurement error | Not Required |
| <i><u>Sectioning</u></i> | 40 min to >5 hrs | 100 mm ² | 1 to 2 mm | 10 | Partial Measurement of RS, parts must be cut or machined | Not Required |
| <i><u>Hole drilling</u></i> | 40 min to 2 hrs | 0.5 mm ² | 50 µm | 35 | Geometry, high residual stresses, and high stress gradients | Not Required |

Residual Stress Results for Various Methods on Shot Peened Gear



Why we prefer X-ray Diffraction (XRD).




- Excellent spatial resolution.
- Can measure in complex geometries such as a gear root.
- Fast 2 to 3 minutes per measurement
- Nondestructive.
- Measures residual stress quantitatively.
- Applicable for metals and ceramics.

PROTO
MANUFACTURING




a world of solutions


XRD in action.



XRDWIN 2.0 Software- Sample Screen Shot



d vs. $\sin^2\psi$ plot



$$\varepsilon = \frac{d - d_0}{d_0} = \frac{\Delta d}{d}$$

$$d_{\phi\psi} = \frac{1}{2} S_2(\sigma_{11}) d_{\psi=0} \sin^2 \psi + \frac{1}{2} S_2(\sigma_{13}) d_{\psi=0} \sin 2\psi + S_1 d_{\psi=0} (\sigma_{11} + \sigma_{22} + \sigma_{33}) + d_{\psi=0}$$

- **Measurements of atomic spacing will give the strain of the material.** $\varepsilon_{\phi\psi} = \frac{d_{\phi\psi} - d_0}{d_0}$
- **Strain is converted to stress via Hook's Law:** $\varepsilon = \frac{\sigma}{E}$

$$\varepsilon_{\phi\psi} = \frac{d_{\phi\psi} - d_0}{d_0} = \frac{1}{2} S_2 \sigma_{11} \sin^2 \psi + \frac{1}{2} S_2 \sigma_{33} \sin^2 2\psi - S_1 (\sigma_{11} + \sigma_{22} + \sigma_{33})$$

Where: ε = measured strain from Bragg's Law
 σ = stress in sample
 ψ and ϕ = measurement direction

Converting from strain to stress.

- XEC can be determined for an alloy using a 4- point bend apparatus.
- XEC is known for most common alloys.



Standards & Guidelines

- SAE HS784 – RS measurement
- ASTM E915 – RS measurement
- ASTM E1426 – 4 pt bend XEC
- ASM Handbook Vol.11 – General guidelines

Accuracy of XRD for residual stress

- Measurement error can be as low as ± 10 MPa.
- X-ray beam can be sized from 0.040 mm to 5 mm to analyze features.
- Measurement time is 2 to 5 minutes per location. (MET). A few seconds for (SET)
- Works on highly ordered polycrystalline materials only (i.e. metals and ceramics.)

Common XRD measurement geometries (detector and beam arrangement) for RS

- $\sin^2\psi$ Multiple Exposure
- $\sin^2\psi$ Single Exposure
- $\sin^2\chi$ Multiple Exposure
- $\sin^2\chi$ modified Multiple Exposure
- $\sin^2\chi$ Single Exposure
- $\cos\alpha$

Each has its own advantages and disadvantages

Residual Stress Measurement Examples

Stress profiling through a part.


- XRD is a surface techniques. X-ray beam only penetrates 5 to 10 microns into the material.
- Electropolish to remove layers to generate stress vs. depth curves.



Electropolishing Spot




Stress profiling through a component



Quality Control of a Peened Spring

- Compare the residual stress in vintage springs, current production with increased field failure incidence and improved peening process.

Quality Control of a Peened Spring



The future for residual stress in component manufacturing.

- Improved quality control of manufacturing processes.
- Increase fatigue life of critical components.
- Use of residual stress as a gauge of the health of in-service components.
- Decrease costs by using lower cost materials with designed in residual stress to enhance the performance of the material.

The Equipment

iXRD – MG40 Goniometer and Field Stand #2

Residual Stress & Retained Austenite




Features

| | |
|--------------|------------------------------------|
| Control unit | iXRD |
| Power | 300 Watts |
| Goniometer | MG40 |
| Geometry | iso, modified- χ |
| Field Stand | #2 |
| Travel | 100 or 200 mm Z axis, Cobra Arm |

iXRD - MGR40 Goniometer and Field Stand #4

Residual Stress Mapping &
Retained Austenite



Features

| | |
|--------------|--------------------------------|
| Control unit | iXRD |
| Power | 300 Watts |
| Goniometer | MGR40 |
| Geometry | iso, modified- χ |
| Field Stand | #4 |
| Travel | 100 mm X,Y Z axis Cobra Arm |

iXRD Floor Stand - MGR40 Goniometer and Field Stand #4



Residual Stress Mapping & Retained Austenite

Features

| | |
|--------------|-------------------------------------|
| Control unit | iXRD |
| Power | 300 Watts |
| Goniometer | MGR40 |
| Geometry | iso, modified- χ |
| Field Stand | #4 |
| Travel | 100 mm X,Y Z axis Cobra Arm |
| Floor Stand | 920 mm Z-axis and 560 mm Y-axis. |

iXRD Combo

Residual Stress & Retained Austenite



Features

| | |
|--------------------|--|
| Control unit | iXRD |
| Power | 300 Watts |
| Goniometer | MG40 |
| Geometry | Iso, modified- χ |
| Sample Positioning | 200 mm X,Y Z axis Phi rotation stage Cobra Arm |
| Cabinet Dimensions | 1.6 x 1.1 x 1.8 m |

iXRD Gantry



Residual Stress & Retained Austenite

Features

| | |
|--------------------|--|
| Control unit | iXRD |
| Power | 300 Watts |
| Travel | 760 mm Z axis 2100 x 650 mm XY axis 360° ϕ rotation |
| Goniometer | MGR40 |
| Geometry | iso, modified- χ |
| Cabinet Dimensions | 2700 x 1100 x 2600 mm |

LXRD

Residual Stress & Retained Austenite



Features

| | |
|--------------------|---|
| Control unit | LXRD |
| Power | 1200 Watts |
| Travel | 500 mm Z axis 200 mm X,Y stage 360° ϕ rotation stage |
| Goniometer | MG2000 |
| Sample Positioning | Mapping Stages |
| Geometry | Iso, modified- χ |
| Cabinet Dimensions | 1.1 x 0.7 x 1.9 m |

LXRD Widebody



Residual Stress & Retained Austenite

| Features | |
|--------------------|---|
| Control unit | LXRD |
| Power | 1200 Watts |
| Travel | 700 mm Z axis 300 mm X,Y stage 360° ϕ rotation stage |
| Goniometer | MG2000 |
| Geometry | Iso, modified- χ |
| Cabinet Dimensions | 1.1 x 1.1 x 1.9 m |

LXRD Microarea



Residual Stress & Retained Austenite

Features

| | |
|-----------------------|---|
| Control unit | LXRD |
| Power | 3000 Watts |
| Travel | 300 mm Z axis 100 mm X,Y stage 360° ϕ rotation -45° to +51° χ axis |
| Goniometer | MG2000+Chi axis |
| Geometry | Iso, side inclination, modified- χ |
| Cabinet Dimensions | 1.1 x 0.8 x 1.9 m |

mXRD Ultraportable



Residual Stress

Features

| | |
|--------------|--------------|
| Control unit | mXRD |
| Power | 40 Watts |
| Travel | 50 mm Z axis |
| Goniometer | MG15 |
| Geometry | iso |

LXRD Modular Mapping



Residual Stress & Retained Austenite

| Features | |
|--------------------|---|
| Control unit | LXRD |
| Power | 3000 Watts |
| Travel | 500 mm Z axis 200 mm X,Y stage 360° ϕ rotation |
| Goniometer | MG2000 |
| Geometry | Iso, modified- χ |
| Cabinet Dimensions | 2.5 x 1.9 x 2.0 m |

LXRD Gantry



Residual Stress & Retained Austenite

Features

| | |
|--------------------|---|
| Control unit | LXRD |
| Power | 3000 Watts |
| Travel | 800 mm Z axis 2500 mm X,Y axis 360° ϕ rotation |
| Goniometer | MGR2000 |
| Sample Positioning | Gantry System |
| Geometry | Iso, modified- χ |
| Dimensions | 3.8 x 3.6 x 4.0 m |

Thank You